

Annexure D

BUILDING SAFETY CERTIFICATE

No. 018/भवन

Dated: 23/06/2025

It is certified that the existing building **St. Don Bosco International School** (name of the building or premises) at **Bhaisahi Road, Rudrapur, Deoria** (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	B+3 Floor 1 Block	—	—	—	—	—


The building is owned/occupied by **St. Don Bosco International School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Assistant Engineer, PWD, Deoria** (Name of Department/Govt.) on **18/06/2025** (date of inspection) in the presence of **Dr. Virendra Kumar Sahani R/o Salempur, District- Deoria** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **23/06/2025** for a period **5** of years in accordance with rule and subject to compliance of the specific conditions as appended.


- 1.All NBC Conditions are follow by the institution.
- 2.In the Period of this certificate all NBC safety points are follow by institution.
- 3.This Period if any problem due to NBC the department are not responsible.
- 4.This Period if any problem due to NBC the institution are responsible all situations.

Issued on **23 /06/2025** at **Assistant Engineer, PWD Deoria** by **Deoria**.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 
सहायक अभियन्ता
Name : प्रान्तीय खण्ड, लोअनिर्वि० देवरिया
Designation : **ASSISTANT ENGINEER**
Name & Address of Department/ Office: **DEORIA**


P. Verma
Principal
St. Don Basco International School
Rudrapur-Deoria(U.P.)274204


Manager
St. Don Basco International School
Rudrapur-Deoria(U.P.)274204