


PERFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. -22/2025-26

Dated: 24.07.2025

It is certified that an inspection team headed by **Raghvendra Kumar Mishra, Chemist, District Level Water Analysis Laboratory, Deoria** (Name of officers with designation) from **UP Jal Nigam (Rural) Deoria** (Name of Department/office) Inspected **ST. DON BOSCO INTERNATIONAL SCHOOL, BHAI SAHI ROAD, RUDRAPUR, DEORIA** (Name & Address of the school) on **23.07.2025** (Date of inspection) and on the basis of water test report (Attached) Report no: **WTD/007/JULY(25-26)** dated **23.07.2025** of **District Level Water Analysis Laboratory, Deoria (PHED-lab)** certified that the **ST. DON BOSCO INTERNATIONAL SCHOOL, BHAI SAHI ROAD, RUDRAPUR, DEORIA** (Name of school) has safe drinking water facilities for the students and staffs of the institution. School is also maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central /state /U.T.Govt.

This certificate is valid till **01 Year** from date of issue. In case, if there is any change in Drinking Source /gone under maintenance before Expiry of certificate, then this certificate will be no more valid. So to avoid this problem School is advice to send Drinking Water Sample on Regular Interval to District Level Water Analysis Laboratory, Deoria.

Signature with Seal  Assistant Engineer
Division Office.
U.P. Jal Nigam (Rural)
Deoria


Name Er. Viswajeet Verma

Designation Assistant Engineer

Name & Address of the office/Department

Uttar Pradesh Jal Nigam Rural, Bhujauli Colony,
Deoria

To


Principal

St. Don Basco International School
Rudrapur-Deoria(U.P.)274204


Manager

St. Don Basco International School
Rudrapur-Deoria(U.P.)274204

PRINCIPAL,

ST. DON BOSCO INTERNATIONAL SCHOOL

BHAI SAHI ROAD, RUDRAPUR, DEORIA (Name & Address of the institution)

Note: The certificate is to be issued by authorized officer/PHED Lab/local bodies.